

-14-

METHOD FOR CONTROLLING PRESS CONVEYORS

ABSTRACT

5 A control method of the parts constituting the chain conveyors used in presses, which allows carrying out measurements on them while the conveyors are operating, with no physical contact with said parts, and whose accuracy is independent of the conveyor speed, which method consists of counting the pulses from a clock signal during the time the element to be measured is passing.

EXPRESS MAIL NO.:
EV327549165US